



Securicon, LLC
5400 Shawnee Road
Suite 206
Alexandria, VA 22312

March 9, 2020

MSA Safety
1991 Tarob Court
Milpitas, CA 95035

To Whom It May Concern,

Between September 2019 and February 2020, Securicon conducted a series of vulnerability assessments of the FieldServer Gateway device and firmware (version B0011-7.1.0-SECURE-GATEWAY-5-BETA-ARMV7).

The final retest of the device in February 2020 by Securicon found only two medium vulnerabilities. Both vulnerabilities can be fully mitigated by the user selecting an available secure option that enables secure and/or encrypted communication. Details of these findings can be found in the attached remediation report.

With the mitigations available to the user in place and chosen Securicon can attest that this device and associated firmware, as tested, are secure.

Paul W. Hurley
CEO